

### Task and Site Specific Respirator Chart

Department	Plant	Task	Respirator	Possible Exposure
Yard	Cen-11	Loading Silica	Sundstrom SR90	Silica
Plant-Flt Mtn/Yard	Cen-11	Welding	3M-8214	Fumes
Yard	Cen-11	Dosing Loads with Cal-Tite	Sundstrom SR90	Fumes
Yard	Cen-11	Chipping Pre-Mixer	Sundstrom SR90	Dust Silica Fumes